

No.	Timestamp	Lantern Type	material	Bracket type	Pole bracket	Structural condition	comments on structural condition
1	9/25/2018 9:13:44	Thorn	Steel	P/T	no	1 - new	Good
2	9/25/2018 9:24:24	Phillips sox	Concrete	Concrete o.50	no	2-good	Good condition Stanton Waverley
3	9/25/2018 9:44:43	Phillips	Steel	Hockey sticick0.25	no	2-good	Good
4	9/25/2018 9:54:20	Phillips	Concrete	Concrete 0.5	no	2-good	Stanton stavelet
5	9/25/2018 10:04:25	Phillips	Concrete	Concete 0.3	no	2-good	Good
6	9/25/2018 10:13:38	Phillips	Concrete	Concrete 0.3	no	2-good	Door banded
7	9/25/2018 10:23:16	Phillips	Steel	Concrete 0.3	no	2-good	Stanton staveley
8	9/25/2018 10:34:18	Phillips	Concrete	Concrete 0.3	no	2-good	Door triple banded
9	9/25/2018 10:44:34	Phillips	Concrete	Concrete 0.3	no	2-good	Good
10	9/25/2018 10:56:33	Phillips	Concrete	Concrete 0.3	no	2-good	Goog
11	9/25/2018 11:03:47	Phillips	Concrete	Concrete 0.3	no	2-good	Good no access to door
12	9/25/2018 11:11:26	Phillips	Concrete	Concrete 0.3	no	2-good	Good
13	9/25/2018 11:37:45	Phillips	Concrete	Concrete 0.3	no	2-good	Footpath Square good condition
14	9/25/2018 11:42:36	Phillips	Concrete	Concrete 0.3	no	2-good	Good
15	9/25/2018 12:01:26	Phillips	Concrete	Concrete 0.3	no	2-good	Good 2 cables in both columns
16	9/25/2018 12:07:44	Phillips	Concrete	Concrete0.3	no	2-good	Good
17	9/25/2018 12:13:13	Phillips	Concrete	Concrete 0.3	no	2-good	Good
18	9/25/2018 12:49:54	Phillips	Concrete	Concrete 0.3	no	3 - fair	Damage at door
19	9/25/2018 12:57:08	Phillips	Concrete	Concrete 0.3	no	2-good	Good
20	9/25/2018 13:02:52	Phillips	Steel	Hockey stick	no	2-good	Good
21	9/25/2018 13:10:37	Phillips	Steel	Pole bracket with GRP box	yes	2-good	
22	9/25/2018 13:23:23	Phillips	Steel	Hockey stick	no	2-good	Good
23	9/25/2018 13:28:49	Thorn	Concrete	Concrete 0.3	no	2-good	Good
24	9/25/2018 13:36:41	Gamma 6 thorn	Concrete	Post top sleeve	no	2-good	Good has sleeve extension fitted close overhead lines
25	9/25/2018 13:43:43	Phillips	Steel	Pole bracket with GRP box	yes	2-good	Good
26	9/25/2018 14:01:55	Phillips	Concrete	Concrete 0.5	no	2-good	Good
27	9/25/2018 14:06:04	Phillips	Concrete	Concrete	no	2-good	Good
28	9/25/2018 14:11:21	Bvi	Steel	Post top	no	1 - new	Goog
29	9/25/2018 14:15:54	Phillips	Concrete	Concrete 0.5	no	2-good	Good
30	9/25/2018 14:20:16	Phillips	Steel	Hockey stick	no	2-good	Good
31	9/25/2018 14:25:40	Phillips	Concrete	Concrete 0.5	no	2-good	Good
32	9/25/2018 14:31:56	Phillips	Concrete	Concrete o.5	no	2-good	No access to door hedge
33	9/25/2018 14:36:29	Phillips	Concrete	Concrete o.5	no	2-good	Good
34	9/25/2018 14:41:17	Phillips	Steel	Hockey stick	no	2-good	Good
35	9/26/2018 9:19:56	Not known to check	Concrete	Concrete 0.3	no	3 - fair	Door banded no access hedge overgrown
36	9/26/2018 9:25:12	BVI INDUSTRIA	Steel	Post top	no	1 - new	Good
37	9/26/2018 9:40:19	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good painted
38	9/26/2018 9:45:40	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good no access to door overgrown hedge
39	9/26/2018 9:50:39	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good
40	9/26/2018 9:56:09	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good
41	9/26/2018 10:01:24	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good painted
42	9/26/2018 10:06:10	Thorn	Steel	Pole bracket	yes	2-good	GDP BOX FITTED
43	9/26/2018 10:12:39	Thorn	Steel	Pole bracket	yes	1 - new	GDP BOX FITTED
44	9/26/2018 10:17:11	Thorn	Steel	Pole btacket	yes	1 - new	GDP BOX FITTED
45	9/26/2018 10:22:35	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good
46	9/26/2018 10:36:16	Thorn	Steel	Hockey stick	no	1 - new	Good painted
47	9/26/2018 10:40:41	Thorn	Steel	Hockey stick	no	1 - new	Good painted
48	9/26/2018 10:46:35	Thorn	Steel	Wall bracket painted black	yes	1 - new	Good steel box
49	9/26/2018 10:52:59	Thorn	Steel	Wall bracket cast black	yes	1 - new	Wall bracket supply from feeder pillar black
50	9/26/2018 11:09:28	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good painted
51	9/26/2018 11:22:13	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good painted
52	9/26/2018 11:33:15	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good painted
53	9/26/2018 11:46:47	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good painted
54	9/26/2018 11:52:14	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good painted
55	9/26/2018 11:56:57	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good painted
56	9/26/2018 12:01:04	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good painted
57	9/26/2018 12:07:16	Thorn	Steel	Pole bracket	yes	2-good	GDP BOX FITTED
58	9/26/2018 12:14:43	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good painted

No.	Timestamp	Lantern Type	material	Bracket type	Pole bracket	Structural condition	comments on structural condition
59	9/26/2018 12:20:08	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good painted
60	9/26/2018 12:24:25	Thorn	Steel	Hockey stick	no	1 - new	Good painted
61	9/26/2018 12:31:14	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good painted
62	9/26/2018 12:36:21	Thorn	Steel	Hockey stick0.5	no	1 - new	Good painted
63	9/26/2018 12:41:56	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good painted
64	9/26/2018 12:47:16	Thorn	Steel	Hockey stick 0.5	no	1 - new	Good paintd
65	9/26/2018 13:35:01	Phillips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
66	9/26/2018 13:40:42	BVI	Steel	Post top	no	1 - new	Good
67	9/26/2018 13:47:14	Phillips	Steel	Hockey stick	no	2-good	Good painted
68	9/26/2018 13:56:24	Phillips	Steel	Hockey stick 0.3	no	2-good	Painted aged
69	9/26/2018 14:00:50	Phillips	Steel	Hockey stick 0.3	no	2-good	Painted aged
70	9/26/2018 14:05:31	Phillips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
71	9/26/2018 14:11:38	Phillips	Steel	Hockey stick 0.3	no	2-good	Good painted aged no door access overgrown hedge
72	9/26/2018 14:17:12	Phillips	Steel	Hockey stick 0.3	no	2-good	Good painted aged shade missing no access to door ove
73	9/26/2018 14:22:22	Phillips	Steel	Hockey stick 0.3	no	2-good	Good painted aged no door access overgrown hedge
74	9/26/2018 14:30:18	Phillips	Steel	Hockey stick 0.5	no	2-good	On pathway should be R/L column
75	9/26/2018 14:36:16	Gamma 6	Steel	Post top	no	2-good	Good painted aged no access to column dog fowling bin
76	9/26/2018 14:44:43	Phillips	Steel	Hockey stick 0.5	no	2-good	Painted aged
77	9/26/2018 14:49:19	Phillips	Concrete	Concrete	no	3 - fair	Door banded shade missing
78	9/26/2018 14:53:36	Phillips	Concrete	Concrete 0.3	no	2-good	Door banded good
79	9/28/2018 9:47:14	Phillips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
80	9/28/2018 9:52:05	Phillips	Concrete	Concrete 0.5	no	3 - fair	Door banded
81	9/28/2018 9:56:58	Phillips	Steel	Hockey stic 0.3	no	2-good	Good painted aged
82	9/28/2018 10:03:01	Phillips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
83	9/28/2018 10:08:42	Phillips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
84	9/28/2018 10:16:36	Phillips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
85	9/28/2018 10:21:51	Phillips	Steel	1 meter steel	no	2-good	Good
86	9/28/2018 10:34:25	Phillips	Steel	Concrete 0.5	no	3 - fair	Door banded
87	9/28/2018 11:33:19	Phillips	Steel	Hockey stick	no	2-good	Good painted aged
88	9/28/2018 11:39:12	Phillips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
89	9/28/2018 11:44:45	Phillips	Concrete	Concrete spoiling at top	no	4 - poor	Column wooing door banded
90	9/28/2018 11:50:51	Phillips	Concrete	Concrete	no	3 - fair	Door banded
91	9/28/2018 11:56:11	Phillips	Concrete	Post top	no	4 - poor	Can't tell condition covered no access to door
92	9/28/2018 12:04:28	Thorn	Steel	Hockey stick 0.3	no	2-good	Good painted aged
93	9/28/2018 12:29:28	Phillips	Concrete	Concrete 0.5	no	2-good	
94	9/28/2018 12:35:43	BVI INDUSTRIA	Steel	Hockey stick	no	1 - new	Good
95	9/28/2018 12:44:12	Phillips	Concrete	Concrete 0.3	no	2-good	
96	9/28/2018 13:00:13	Phillips	Concrete	Concrete 0.5	no	2-good	Good
97	9/28/2018 13:28:57	Phillips	Steel	Pole bracket	yes	2-good	GDP BOX FITTED
98	9/28/2018 13:49:33	BVI Industria	Steel	Hockey stick 0.3	no	3 - fair	No access due to overgrown vines
99	9/28/2018 13:54:44	Phillips	Steel	Hockey stick 0.3	no	2-good	Good dayburning
100	9/28/2018 14:10:52	Phillips	Concrete	Concrete	no	2-good	Good day burning
101	9/28/2018 14:16:44	Phillips	Steel	Hockey stick 0.3	no	2-good	Sign attached with post no access to door overgrown vin
102	9/28/2018 14:38:00	BVI INDUSTRIA	Concrete	Steeve sleeve fitted 0.3	no	2-good	Good
103	2018-09-28	BVI Indudtria	Concrete	Sleeve fitted 0.3	no	3 - fair	Good door banded
104	9/28/2018 14:50:56	BVI Indudtria	Concrete	Steel sleeve fitted 0.3	no	2-good	Good
105	9/28/2018 14:59:21	No known	Concrete	Concrete0.350	no	2-good	Good
106	10/2/2018 10:03:22	Phillips	Steel	Steel 0.5	yes	2-good	GDP BOX FITTED
107	10/2/2018 10:09:05	Thorn	Steel	Steel 0.5	yes	2-good	GDP BOX FITTED
108	10/2/2018 10:27:47	Phillips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
109	10/2/2018 10:33:50	Phillips	Steel	Steel	no	2-good	Good 8 meter
110	10/2/2018 10:37:33	Phillips	Steel	Hockey stick 0.5	no	1 - new	Good
111	10/2/2018 10:42:00	Phillips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
112	10/2/2018 11:00:01	Not known	Steel	Cast steel	yes	3 - fair	Old type bracket and lantern overgrown trees
113	10/2/2018 11:28:00	Thorn	Steel	Hockey stick0.3	no	2-good	Good
114	10/2/2018 11:32:06	Thorn	Steel	Hockey stick 0.3	no	2-good	Good
115	10/2/2018 11:36:37	Industria 2000 lantern footv	Steel	Post top	no	2-good	Good painted aged

No.	Timestamp	Lantern Type	material	Bracket type	Pole bracket	Structural condition	comments on structural condition
116	10/2/2018 11:41:13	Not known footway light to	Steel	Post top	no	3 - fair	Door damage painted aged
117	10/2/2018 11:45:30	Not know to check	Steel	Post top	no	2-good	Good
118	10/2/2018 11:50:15	Industria 2000 footway ligh	Steel	Post top	no	2-good	Good column learning
119	10/2/2018 13:09:39	Thorn	Steel	Post top	no	2-good	Good pathway blocked gone
120	10/2/2018 13:14:18	Thorn	Steel	Post top	no	2-good	Good R/ L Column
121	10/2/2018 13:17:51	Thorn	Steel	Post top	no	2-good	Good R/L Column
122	10/2/2018 13:22:12	Thorn	Steel	Post top	no	2-good	Good
123	10/2/2018 14:45:13	Philips	Steel	Steel	yes	2-good	GDP BOX FITTED
124	10/2/2018 14:49:27	Philips	Steel	Steel	yes	2-good	Good GDP BOX FITTED
125	10/3/2018 9:26:11	Philips	Concrete	Concrete 0.3	no	2-good	Goog
126	10/3/2018 9:30:52	Philips	Concrete	Concrete 0.3	no	2-good	Good
127	10/3/2018 9:35:14	Philips	Concrete	Concrete 0.3	no	2-good	Good
128	10/3/2018 9:39:23	Thorn	Concrete	Hockey stick 0.3	no	1 - new	Good
129	10/3/2018 9:44:15	Philips	Concrete	Concrete	no	2-good	Good
130	10/3/2018 9:48:05	Philips	Concrete	Concrete 0.3	no	2-good	Good
131	10/3/2018 9:52:00	Philips	Concrete	Concrete 0.3	no	2-good	Good
132	10/3/2018 9:55:48	Philips	Concrete	Concrete	no	2-good	Good
133	10/3/2018 10:01:53	Philips	Concrete	Concrete	no	2-good	Good
134	10/3/2018 10:05:47	Philips	Concrete	Concrete 0.3	no	2-good	Good
135	10/3/2018 10:11:32	Philips	Concrete	Concrete 0.3	no	2-good	Goog
136	10/3/2018 10:17:15	Philips	Concrete	Concrete o.3	no	2-good	Good day burning
137	10/3/2018 10:21:38	Philips	Concrete	Concrete 0.3	no	2-good	Good
138	10/3/2018 10:26:02	Philips	Concrete	Concrete 0.3	no	2-good	Good
139	10/3/2018 10:30:43	Philips	Concrete	Concrete 0.3	no	2-good	Good
140	10/3/2018 11:15:41	Philips	Steel	Hockey stick 0.3	no	2-good	Good
141	10/3/2018 11:20:47	Philips	Concrete	Steel sleeve 0.3	no	2-good	Good column has been sleeved
142	10/3/2018 11:24:58	BVI INDUSTRIA	Steel	Post top	no	1 - new	Good
143	10/3/2018 11:52:10	Philips	Steel	Hockey stick 0.5	no	2-good	Good painted aged
144	10/3/2018 11:56:37	Philips	Concrete	Steel sleeved 0.3	no	2-good	Good column sleeved at front of kerb
145	10/3/2018 12:00:55	Philips	Concrete	Steel sleeved 0.3	no	2-good	Good column sleeved front of kerb
146	10/3/2018 12:53:25	Thorn	Steel	Hockey stick 0.3	no	2-good	Good light shield fitted
147	10/3/2018 12:57:22	Thorn	Steel	Hockey stick 0.3	no	2-good	Good lantern in overgrown tree
148	10/3/2018 13:00:54	Thorn	Steel	Hockey stick 0.3	no	2-good	Good
149	10/3/2018 13:05:16	Thorn	Steel	Hockey stick 0.3	no	2-good	Good
150	10/3/2018 13:09:16	Thorn	Steel	Hockey stick 0.3	no	1 - new	Good
151	10/3/2018 13:12:32	Thorn	Steel	Hockey stick 0.3	no	1 - new	Good
152	10/3/2018 13:16:29	Thorn	Steel	Hockey stick 0.3	no	2-good	Good
153	10/3/2018 13:20:10	Thorn	Steel	Hockey stick 0.3	no	2-good	Good
154	10/3/2018 13:34:00	Philips	Steel	Hockey stick 0.3	no	2-good	Good
155	10/3/2018 13:37:29	Thorn	Steel	Hockey stick 0.3	no	2-good	Good
156	10/3/2018 13:44:29	Philips	Concrete	Cocrete 0.3	no	3 - fair	Concrete bracket twisted
157	10/3/2018 13:49:02	Philips	Concrete	Concrete 0.3	no	2-good	Good
158	10/3/2018 13:53:02	Thorn	Steel	Hockey stick 0.3	no	2-good	Good FITTED with shield
159	10/3/2018 13:57:15	Thorn	Steel	Hockey stick 0.3	no	2-good	Good
160	10/3/2018 14:02:56	Philips	Concrete	Concrete 0.3	no	2-good	Good door has hole in it
161	10/3/2018 14:07:40	Philips	Concrete	Concrete 0.3	no	2-good	Good in part of driveway
162	10/4/2018 9:20:25	Philips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
163	10/4/2018 9:24:55	CU GAMMA 6	Concrete	Post top	no	2-good	Good day burning
164	10/4/2018 9:31:56	Cu gamma 6	Concrete	Post top	no	3 - fair	Door banded day burning
165	10/4/2018 9:35:52	Philips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
166	10/4/2018 9:42:34	Philips	Steel	Hockey stick 0.3	no	2-good	Good
167	10/4/2018 9:46:06	Philips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
168	10/4/2018 9:49:48	Gamma 6	Concrete	Post top	no	2-good	Good
169	10/4/2018 9:53:46	Gamma 6	Concrete	Post top	no	2-good	Good
170	10/4/2018 9:57:48	Philips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
171	10/4/2018 10:02:40	Gamma 6	Steel	Post top	no	2-good	Good day burning
172	10/4/2018 10:07:39	Gamma 6	Steel	Post top	no	4 - poor	Spoiling at top door banded
173	10/4/2018 10:13:00	Gamma 6	Concrete	Post top	no	2-good	Good day burning

No.	Timestamp	Lantern Type	material	Bracket type	Pole bracket	Structural condition	comments on structural condition
174	10/4/2018 10:17:08	Philips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
175	10/4/2018 10:21:29	Philips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
176	10/4/2018 10:30:00	Philips	Steel	Hockey stick 0.5	no	2-good	Good
177	10/4/2018 10:36:18	Philips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
178	10/4/2018 10:40:22	Philips	Concrete	Concrete 0.3	no	2-good	Good
179	10/4/2018 10:44:41	Philips	Concrete	Concrete 0.3	no	3 - fair	Good door banded column learn slightly
180	10/4/2018 10:50:50	Thorn	Steel	Steel 0.3	no	2-good	Good door buried below ground
181	10/4/2018 11:00:37	Philips	Steel	Hockey stick 0.3	no	2-good	Good painted aged
182	10/4/2018 11:14:30	BVI INDUSTRIA	Steel	Post top	no	2-good	Good Painted aged R/L Column
183	10/4/2018 11:18:30	BVI INDUSTRIA	Steel	Post top	no	2-good	Good painted aged dog bin attached to column lantern tv
184	10/4/2018 11:23:44	Not know old	Steel	Concrete spoiling	no	3 - fair	Column good day burning
185	10/4/2018 11:28:10	Not know poss Gec	Concrete	Concrete 0.3	no	2-good	Good
186	10/4/2018 11:33:15	Not known poss Gec	Concrete	Cocrete 0.3	no	2-good	Good day burning
187	10/4/2018 12:01:56	Gamma 6	Steel	Post top	no	2-good	Good aluminium column door banded
188	10/4/2018 12:06:20	ASD	Steel	Post top	no	2-good	Good Ali column door banded
189	10/4/2018 12:10:22	Thorn	Steel	Hockey stick0.5	no	1 - new	Good
190	10/4/2018 12:15:13	Gamma 6	Concrete	Post top	no	2-good	Good doorvbanded
191	10/4/2018 12:20:02	Gamma 6	Steel	Post top	no	2-good	Good Ali column door banded
192	10/4/2018 12:29:04	ASD	Steel	Post top	no	1 - new	Good
193	10/4/2018 12:32:40	Gamma 6	Steel	Post top	no	2-good	Good Ali column banded
194	10/4/2018 12:37:07	Gamma 6	Steel	Post top	no	2-good	Good Ali column door banded
195	10/4/2018 13:25:41	Philips	Concrete	Concrete 0.3	no	2-good	Good dog bin attached
196	10/4/2018 13:29:51	Philips	Concrete	Concrete 0.3	no	2-good	Good
197	10/4/2018 13:34:09	Philips	Concrete	Concrete 0.3	no	2-good	Good
198	10/4/2018 13:48:35	Not known poss Gec	Concrete	Concrete 0.3	no	2-good	Good day burning shade missing
199	10/4/2018 14:04:22	Philips	Steel	Hocky stick 0.3	no	2-good	Good painted aged
200	10/8/2018 9:21:45	Philips	Concrete	Concrete 0.5	no	2-good	Good
201	10/8/2018 9:25:23	Philips	Concrete	Concrete	no	2-good	Good
202	10/8/2018 9:29:07	Philips	Concrete	Concrete	no	2-good	Good
203	10/8/2018 9:33:38	Philips	Concrete	Cocrete 0.5	no	2-good	Good
204	10/8/2018 9:37:39	Philips	Concrete	Concrete	no	2-good	Good
205	10/8/2018 9:43:03	Philips	Concrete	Concrete 0.5	no	2-good	Good
206	10/8/2018 9:47:08	Philips	Concrete	Concrete 0.5	no	2-good	Good
207	10/8/2018 9:50:40	Philips	Concrete	Concrete 0.5	no	2-good	Good bracket twisted
208	10/8/2018 9:56:55	Philips	Concrete	Concrete 0.5	no	2-good	Good
209	10/8/2018 10:05:52	Philips	Concrete	Concrete 0.5	no	2-good	Good
210	10/8/2018 10:34:21	Philips	Concrete	Cocrete extention 1.0	no	5 - dangerous requires att	Poor door banded bracket taped up spoiling dog bin atta
211	10/8/2018 10:39:00	BVI INDUSTRIA	Concrete	Steel extention bracket 1.5	no	3 - fair	Door banded
212	10/8/2018 10:44:25	Not know could be Gec	Concrete	Cocrete 0.3	no	2-good	Good
213	10/8/2018 10:48:36	Philips	Steel	Steel0.75	yes	4 - poor	Poor Girl BOX door missing
214	10/8/2018 11:05:15	Philips	Concrete	Concrete 0.3	no	2-good	Good
215	10/8/2018 11:09:20	Philips	Concrete	Concrte 0.5	no	2-good	Good door access in overgrown hedge
216	10/8/2018 11:13:55	Philips	Concrete	Concrete 0.5	no	2-good	Good
217	10/8/2018 11:18:04	Philips	Concrete	Concrete 0.5	no	2-good	Good
218	10/8/2018 11:58:28	Philips	Steel	Hockey stick 0.3	no	2-good	Good
219	10/8/2018 12:03:12	Not known	Concrete	Steel	no	2-good	Good door no access overgrown hedge
220	10/8/2018 12:09:49	Not know	Steel	Steel	yes	4 - poor	Poor overgrown and listing down could be broken
221	10/8/2018 14:10:28	Philips	Steel	Steel 0.3	no	2-good	Good R/L Column painted aged
222	10/8/2018 14:14:42	Philips	Steel	Steel 0.3	no	3 - fair	Good R/L column painted aged
223	10/8/2018 14:18:35	Philips	Steel	Steel 0.3	no	2-good	Good painted aged R/L column
224	10/8/2018 14:22:24	Philips	Steel	Steel 0.3	no	2-good	Good painted aged R/L column
225	10/8/2018 14:26:43	Philips	Steel	Steel 0.3	no	2-good	Good painted aged R/L column
226	10/8/2018 14:29:55	Philips	Steel	Steel 0.3	no	2-good	Good painted aged R/L column
227	10/8/2018 14:33:28	Philips	Steel	Steel 0.3	no	2-good	Good painted aged R/L column
228	10/8/2018 14:36:56	BVI INDUSTRIA	Steel	Steel 0.5	yes	2-good	Good in trees
229	10/8/2018 14:40:09	Philips	Steel	Steel 0.3	no	2-good	Good painted aged R/L column
230	10/8/2018 14:49:04	Thorn	Steel	Steel 0.5	yes	2-good	Good GDP BOX FITTED

No.	Timestamp	Lantern Type	material	Bracket type	Pole bracket	Structural condition	comments on structural condition
231	10/12/2018 9:55:55	Thorn	Steel	Hockey stiick 0.3	no	2-good	Good painted
232	10/12/2018 9:59:45	Thorn	Steel	Hockey stick 0.3	no	2-good	Good painted no access to door overgrown hedge
233	10/12/2018 10:03:26	Thorn	Steel	Hockey stick 0.3	no	2-good	Good painted
234	10/12/2018 10:08:42	ASD DIAMOND	Steel	Steel 0.75	yes	2-good	God Girl BOX fitted
235	10/12/2018 10:12:01	Thorn	Steel	Hockey stick 0.3	no	2-good	Good painted
236	10/12/2018 10:17:34	Thorn	Steel	Hockey stick 0.3	no	2-good	Good painTed
237	10/12/2018 10:21:15	Thorn	Steel	Hockey stick 0.3	no	2-good	Good painted
238	10/12/2018 10:27:03	Thorn	Steel	Hockey stick 0.3	no	2-good	Good painted
239	10/12/2018 10:50:45	Indusria 2000	Steel	Post top	no	2-good	Good painted
240	10/12/2018 10:53:39	Indusria 2000	Steel	Post top	no	2-good	Good painted
241	10/12/2018 10:57:08	Indusria 2000	Steel	Post top	no	2-good	God painted
242	10/12/2018 11:00:06	Industria 2000	Steel	Post top	no	2-good	Good painted
243	10/12/2018 11:04:29	Bollard	Steel	Bollard	no	3 - fair	1 meter high doorway bollard
244	10/12/2018 11:07:24	Bollard	Steel	Bollard	no	3 - fair	
245	10/12/2018 11:10:36	Bollard	Steel	Bollard	no	3 - fair	1 meter high bollard
246	10/12/2018 11:14:03	Bollard	Steel	Bollard	no	3 - fair	1 meter high bollard
247	10/12/2018 11:16:35	Bollard	Steel	Bollard	no	3 - fair	1 meter high bollard

wattage	Road width	Footway width	Spacing	picture 3
70	5.5	1.9	50.3 to next col	https://drive.google.com/open?id=1jncjOQkvEoQJdMMHY5CDIAgLK3mlbh4E
35	5.5	1.9	50.3 from priovios column	https://drive.google.com/open?id=1bk1laTHZnz4Zadm5tuk_88Fb2IPJPhr1
35	5.7	1.9	41.3	https://drive.google.com/open?id=11SXBKVO-kbHfmBABK99AXtW0nGDqFI43
35	5.7	1.9	47.4	https://drive.google.com/open?id=1O6TgijYwZFqmw8JXbzXVJm4_2MNuH2U-
35	5.7	1.9	39.8	https://drive.google.com/open?id=16uiEh6PYCWJi0fE67zVQfWDqD9i-sM2S_
35	5.7	1.9	39.4	https://drive.google.com/open?id=1pl1ETuQogcoHw0jKf-p24zjnbvkBwhcb_
35	5.1	1.7	39.4	https://drive.google.com/open?id=1BmmJLhzYbHliZwSr23F9Y15ci-cqvE_c
35	13 hammer head	1.7	39.4	https://drive.google.com/open?id=1-Beag46uaz6n_u8fSwg4ehuArPgizf6M
35	5.7	1.9	33.7	https://drive.google.com/open?id=15ol94AorZEIfBU_gw4XcnVxB_E9wx1_
35	5.7	1.9	40.5 in hammer head	https://drive.google.com/open?id=1IXxHCxAmYr1xfqKa9BKqbZyUX9BfRK0i_
35	Hammer head	No fooway	27	https://drive.google.com/open?id=1Oi3jY23kE_Q1XuPdtxj_pR3VT6XVb3JO_
35	5.3 hammer head 40.3	1.9	Hammerhead 40.3	https://drive.google.com/open?id=19JpyFidSfONt_dG_yhm3mT4CXmWfttNO_
35	Hammer head large	Pathway square 1.9	27.6	https://drive.google.com/open?id=1Lc7-ZGaSvEIVvgQsFeljgs_bzmd7P3Et_
35	Pathway around green	1.9	23	https://drive.google.com/open?id=1vM7dvTTSaWpKcTiwsOVI91EjoJxJYJe8_
35	Square1.9	1.7	23	https://drive.google.com/open?id=1zRbp6aAMNsK9nQCtYdw8nGN4vg-t4PtR_
35	5.2	1.7	51.3 mtrs from road enterance	https://drive.google.com/open?id=1CLHVG_gwuBCcdRh-BobGiMyPL_H8rNIO_
35	Hammerhead	1.7	29.2 from first column	https://drive.google.com/open?id=1rAgOF8WVkrb0VAaCSardVN6Ej-G6XxCJ_
35	3,3	1.9	27.3 from junction	https://drive.google.com/open?id=1vnGJ1qI7ZEyJs2VeQ6bbXYdYI4TkAz2R_
35	5.5	No footway	73.6	https://drive.google.com/open?id=1sEO4To8FNND1nJhEYNlgy3Ei9R2DfXrs_
35	4.6	No footway	46.6	https://drive.google.com/open?id=1l8mLkuUP9uE9MmgUO66kDZ1V2eJA91jk_
35	6.6	No footway	34.1	https://drive.google.com/open?id=150ngphJTLydbDi46kyhMVS65ijEaPvZ_
35	4	No footway	18 mtrs from junction	https://drive.google.com/open?id=1i8YF1Q_dOMrx46KyPnn2Dn6rfGMMVNJQ_
50	4.3	No footway	42.2	https://drive.google.com/open?id=1IV77_IJjs_T_c54WDIV10rYIBGvWijm_
35	4	No footway	46.1	https://drive.google.com/open?id=1j7rRY74kVtNdY4NjE4_hQvqfbD5HiEXm_
35	6.0	No footway@	40.3	https://drive.google.com/open?id=1PeZwSWk-aSP6iACH3wgUpj8y31wNTADg_
35	4.1	1.8	15 meters from junction	https://drive.google.com/open?id=1dII4DAmR4CE4-FM6rE506vi1XUGg8OjK_
35	4.1	1.8	35.6	https://drive.google.com/open?id=1zKP9_wRBAN-RE2acnTiOMfyKRgO72lw_
50	4.1	1.8	43,2	https://drive.google.com/open?id=12biyD45mYGY1IZ03OMx1azYcdJfn1mvg_
35	4.1	1.8	47.1	https://drive.google.com/open?id=1vIOfC11av0133pUpDQHsVwDRXLsZITtg_
35	4.1	1.8	41.5	https://drive.google.com/open?id=1rMkUk59BA8oq89HJyFly85ExV8ShOHD_
35	4.1	1.8	44.5	https://drive.google.com/open?id=1SY4QI0S86dHAoTxgnB1Lm3dkDYNurVq8_
35	4.1	1.8	16.4	https://drive.google.com/open?id=1u4khO6CfYJPnUkCTkrW21FIT3YIAFgVW_
35	4.1	1.8	31.2	https://drive.google.com/open?id=1ym0OY2Np99zZIDG_b1nhzEd6TpLhE3GX_
35	4.1	1.8	36	https://drive.google.com/open?id=1dpGHgIH75-sknmMJ1KtpoCGQ0Gjzr80A_
80	Dirt track 3.0	No footway	56	https://drive.google.com/open?id=13IPi6OdiJ0QDKgWzcvkzbD3tF0_0JIF7_
50	3	No footway	56	https://drive.google.com/open?id=1PXQZTy1SDSIXXBVo-JRRjQmC4Sij3Vc0_
45	16.1	1.8	10 meters from junction	https://drive.google.com/open?id=1fBRlgn80crUH5bkI8mfH021hc8wi4pav_
45	4.6	No footway	42.6	https://drive.google.com/open?id=1WIt1MsRFiOmiRhFhhkxmsZpRfaMbmQY_
45	5.3	No footway	32.6	https://drive.google.com/open?id=1H1xImnBrd5AWyPlm6rlzngXhymr3EYkX_
45	9.7	No footway	41.6	https://drive.google.com/open?id=1GScj6_EwaqcbLEqNa5lw-yuMYnIOLQI_
45	7.2	No footway	37.6	https://drive.google.com/open?id=1vTX-F6nLe1zWT90sbqRMNeEhtA6pc3Eb_
45	3.7	No footway	48.4	https://drive.google.com/open?id=1n498zKJnKktBbMYUmTIBh56FUd6_uf_
45	3.7	No footway	33.5	https://drive.google.com/open?id=1Hme5R7rCXdbdTizohHQz5FvVKe3IQzuy_
45	3.5	No footway	31.8	https://drive.google.com/open?id=12Kzy5Kj6du6rhT-mm0-x_Q1PS51jsLtl_
45	2.8	No footway	48	https://drive.google.com/open?id=10IYH894omTdYtOFA6gztXoKtDIPXi1zR_
45	2.8	No footway	37.7	https://drive.google.com/open?id=1KcZwJR4uz17zWw-siBDRrALxXtNOswA4_
45	4.4	No footway	40.3	https://drive.google.com/open?id=1WHECq_IDm6QQPVZ0DcLqLqG93q-ykwn_
45	3.7	No footway	43.3	https://drive.google.com/open?id=1ZkFIA2yX9Pn-xSjTvWNUYs6S4WIEorNb_
45	3.5	No footway	19.8	https://drive.google.com/open?id=1JhDyXEulpQDpjT5We0gYVreYXutB_9jk_
45	4.5	1.5	14.7 meter from junction kilnbank	https://drive.google.com/open?id=1n7Fm2mHZtWP7R5VDik26RvpVuoHFxt6O_
45	4.4	1.7	39.2	https://drive.google.com/open?id=1LWc8_wvpdTprB_tEga4mXh9mjNZJKQ5H
45	4.5	1.8	44.1	https://drive.google.com/open?id=1i28jy51EHFzichJPr7u-uPUGs_Af48Sg
45	6	1.7	10.2 from junction	https://drive.google.com/open?id=1uFobxWzQL9hTq4FLxdkerqSP-Muh3gXZ
45	3	No footway	39.7	https://drive.google.com/open?id=1oJamBztkMr0wUJ4Ga7T0NeZgqrpwLiVw
45	3.5	No footway	41.2	https://drive.google.com/open?id=13jekJ8iuP2IGOPRPaA2H4zTFxcoE5ML
45	3.7	No footway	44.1	https://drive.google.com/open?id=10BI3Uv8iJuyyZnJtIFTfx6CXu1GyhNhm
45	4,6	No footway	43.7	https://drive.google.com/open?id=17gcl4HeCRxgAmwZ8Vp_oSCaTauCl_B-4
45	3.7	No footwat	40.4	https://drive.google.com/open?id=1JMjnp8ZrJ-T5StuyWBmzHxi9osAlcXk

wattage	Road width	Footway width	Spacing	picture 3
45	5.4	2	40.8	https://drive.google.com/open?id=1Bb-0GdbhAr-gL1o6ZRKBuHBkQkzmr5BN
45	3.8	Q.7	17 meters from junction	https://drive.google.com/open?id=1eCwI4FIH0aXq7uHK1Q_7Kul6hVcTLt-5
45	5.9	1.3	30.2	https://drive.google.com/open?id=1LWZN3pE9DhrqY6INuj555MfNjFAnF4Xk
45	5	1.5	8.5 from junction	https://drive.google.com/open?id=1k1ThTBM1JcpX7VUaPOGJ6U3LTm5Ybg-L
45	3.9	1.4	37.7	https://drive.google.com/open?id=1nYiAUsYnbnxNm6vC2ZaLNgZXX9B_5Lnf
45	5	1.4	30.9	https://drive.google.com/open?id=1tqmL2JpHHTX2CWhws3zkwKQUQZ6D8kb5
35	9.6	No footway	On junction	https://drive.google.com/open?id=1ETyDkJIInqHQPW9bc3xPpIUBvCHeyVeq
50	5.8	1.5	71.2	https://drive.google.com/open?id=1GEdu_62GbrWGk91wflfyzW83rgavwhV
50	5.4	1.4	28.7	https://drive.google.com/open?id=14FuPbnetglfCQPQ-2Zp4Ltp3XWxKqExB
35	5.8	1.5	26.3	https://drive.google.com/open?id=1CMQf4r13-5IZ5CXV_6zaAULNw1X5Ob
50	5.8	1.4	43.4	https://drive.google.com/open?id=1USOdQQ3v9LcOCrK4Z8LweRu9Q1kASAT
35	5.8	1.4	54.9	https://drive.google.com/open?id=1zBR2epKjXDTsA5hCHmjzXWgvfwlo5apX
35	5.5	1.0	73.5	https://drive.google.com/open?id=14wIMSdeEhsv7BqjkaR6-efj_NIZHy7o
35	5.5	1	37.2	https://drive.google.com/open?id=1FwBMapYxOoMNXuM4jVj3xXH-d_vwkuD9
35	5.5	1	44.5	https://drive.google.com/open?id=1qe5lmRwEqIVTg_WgcxOmov-o0tJAoppj
35	No road	2	58 from walkmill road	https://drive.google.com/open?id=1sDD_TjTY_7qT0tlcbc19_uEVWDgMXUFz
80	No road	2	26.6	https://drive.google.com/open?id=1tgRM8ISBSlh-F39e1Tf-Xc6QAe6S1hO3
35	No road	2	21.8	https://drive.google.com/open?id=1QlzMtUzlpGUjF4McTVrPGd1_B_75tutf
35	No road	2	29.9	https://drive.google.com/open?id=1Sz8ax39Vd4NrvToejSZG4UFfcO4U4jnt
35	No road	1.5	32.2	https://drive.google.com/open?id=1nr5T8AbotVvl_0toJTtxG89xNhd9Khr
35	7.4	1.8	On junction	https://drive.google.com/open?id=1X5v9GWZdtHa_yucph69dSMHUVMqgOOVt
35	7.4	1.8	50.5	https://drive.google.com/open?id=11p0wcDvWAlrQTSTYRGzXi9mFai8KAcpD
35	7.4	1.8	43	https://drive.google.com/open?id=1HZxcO4dteRq3tpkZXdJbr-KvXkj9afL2
35	4.8	1.6	14 meters from junction	https://drive.google.com/open?id=1-n_wsn_KcYjh2R8vjTOLaBsQlv_t1Z34
35	7.4	1.8	57.3	https://drive.google.com/open?id=1wkXlam9FGdSwYzP0CjMiZIE8NqN5Ynsg
35	4.5	1.8	69.4 from junction	https://drive.google.com/open?id=1dPbG2UvHxUkkAW6mx8WVD6-b8rGaaH_F
35	4.5	1.8	33.3	https://drive.google.com/open?id=1xQhaeYBAB802RW_an1_4q0Soe_ceau2W
35	5.5	1.8	69.5	https://drive.google.com/open?id=16fyk8Z98nBb31Gi_zxPS54L6NYA5E-Q
35	3	No footway	51.5	https://drive.google.com/open?id=1YzuT2QKRv4NjJUDZvV7ZcDRR0hBUxHnV
35	No roadway	2	45.5	https://drive.google.com/open?id=1GtG1XZJyLhc8z0AMsVyUJMcOjamNKJbu
35	No roadway	2	23	https://drive.google.com/open?id=1e4Vol5GsLbBlq3iBK9JvF-qJcKebGRVH
35	No road way	1.2	53.0 from road	https://drive.google.com/open?id=11j3dxSZOKIQV4UT7b3HsKAZldvk5KTm-
35	No road	1.3	57.0	https://drive.google.com/open?id=1MDoSJ4GfjmtexgP5ACGrkvoFw_PmN2ly
70	No road way	1.3	31 meters from Sutton way	https://drive.google.com/open?id=1iUaNkPXK7X-sE_igqc5and2r8MaNBKw
35	5.0	1.8	52.4 meters from quarry bank road	https://drive.google.com/open?id=1-Z601g-clqQv59Ej28ti-K8w2bYS2At
50	5.5	1.8	32.2	https://drive.google.com/open?id=1-uGAG0Sy9cUu_Z-BVUFF14pgRdFLGHXr
35	5.5	1.8	35.1	https://drive.google.com/open?id=1Sol_k6uvyDlwiJykyiR4XiQrKzxc2N2E
35	5.5	1.8	45.5	https://drive.google.com/open?id=1ZKvkSTeW09U3R_pSHD2yECnvybIRsmlK
35	5.5	1.8	8 meters from junction	https://drive.google.com/open?id=1B-nMhB8E4o-vE5qd5iyTUYd9MbxVYW8A
50	6.01st column	1	1st column	https://drive.google.com/open?id=13c0eUOWf0vomKjJEohexV-5t0S0Unw8-
35	6	1	60	https://drive.google.com/open?id=1ENRCEQGlfjjaV38SHWe4ZP2r15mYZx5a
35	7.3	1.8	48.0 from col opp Bryn	https://drive.google.com/open?id=1KD6_kTmri8xOEw9IEGI-CUTlshEsWHh1
50	7.3	1.8	45.2	https://drive.google.com/open?id=10wEAK0A6SpouR9pJeegD7ZDkkHITV-mB
50	5.1	1.9	30 meters from junction	https://drive.google.com/open?id=1_FQVbY7zmcDWDNuHx2AARoEBh9RqDVM8
50	5.1	1.9	45.9	https://drive.google.com/open?id=1PwVLk9cTbHuFNLcuTCRW2DdlGZepIqi9
50	Hammer head	1.9	42.0 hammer head	https://drive.google.com/open?id=1RjhcY6mrodwcReV2651Oa2tm705eeMni
80	Hammerhead	1.8	52.3 from junction	https://drive.google.com/open?id=1CTVOFn-MeO8TX30yZ2wtDiEKDUqgLCOM
35	3.8	No footway	105.5 meters from junction	https://drive.google.com/open?id=1-k0fkTJuTcdJULgfHXvrkvY0UAxiqcm
70	4.2	No footway	81.6	https://drive.google.com/open?id=1BP0UcHj9akUZOWa7QzmJYkMqfOHDDvdx
35	5.7	1.2	81.5 from junction	https://drive.google.com/open?id=1iVbBr2VSipnlSANG0_aswTqkqXNYOSYb
90	5.9	1.7	110.5	https://drive.google.com/open?id=1iMut386jvTtbKbUW_HBo5dbIUUrXcjU1
35	5.5	1.2	5.5 from junction	https://drive.google.com/open?id=19uzboFLXhrYEMQ_F5aG8fCKdSbATKmpT
35	5.5 top hammer head	1	40	https://drive.google.com/open?id=1M-5NAIkWKQJQy2d1oLr3_MU-p7ylJPtj
80	4.5	No footway	5 meters from junction	https://drive.google.com/open?id=1puexRXyJwgJRRAl-dCtoBmgd6uRdPqTY
50	5	1.7	1st column	https://drive.google.com/open?id=1T0qrSnpcRNZwQl2X5IKBG2AANwvozwGH
50	Hammer head	1.7	21.5	https://drive.google.com/open?id=19l6KLAeUBJwbBZ2DnN-RRt2qXL0nym
70	3.9	Combined with road	30	https://drive.google.com/open?id=1FkORTdLFRbo1r5S-Ze_fPsAyCYL_s87q

wattage	Road width	Footway width	Spacing	picture 3
70	No road	Combined flagged area	19	https://drive.google.com/open?id=1GCrtY_yBG2NO9ZiKQbup1IAEQFT9OxkV
70	No road	Combined flagged 6.0	23.5	https://drive.google.com/open?id=1bjpEln9oyedepDFNv0mhmzF8cludaDwJ
70	No road	Combinde flagged 8.0	29	https://drive.google.com/open?id=13Q2kUyTpRvvOzVsbY3fpV69WWIVzlaP0
70	No road	No footway	Area light	https://drive.google.com/open?id=1m8uHng7Tqee6csRs5g-rE9YsGNqwfALl
70	No road	2.1@	On footway	https://drive.google.com/open?id=16n3VUf1FK_MHSvAiZ4nzo7WxXHjODzaD
70	No road	2.1	42	https://drive.google.com/open?id=1VUwrSpRor74h0pm9ChXnSJ25QoFODjwF
70	3	1	Hammer head garage area	https://drive.google.com/open?id=1tSlgg2jvLLFkccZnKQWfGU2u7FxDkFto
35	4	No fooray	No spacing	https://drive.google.com/open?id=1M2IXznuwhidspEwRTiymAfQnD8dJpg0n
35	3	No footway	59.5	https://drive.google.com/open?id=1v9QhXavlKZID6iWICFcApoducDMGqgl9
35	5.5	1.8	18.0 from junction	https://drive.google.com/open?id=1CRoGqor6Qgg-pW-2rz2okO2SKO3EsQNd
35	5.5 opp cul de sac	1.8	46	https://drive.google.com/open?id=19SiW5udBiZW4fsugWF8-QUkddgtZkBl
35	Cul de sac	1.8	16.5 from junction	https://drive.google.com/open?id=1mfxauKrzNOIUqckbbkxnONVeDxqpfqcd
35	5.5	1.8	38.5	https://drive.google.com/open?id=1BXikPpXsVtNsMQ4hPIUSKvZcLvtz2Qj
35	5.5	1.8	45.5	https://drive.google.com/open?id=1LwBN0lj5_HTMPrEnUurVeagJeooxIU_P
35	5.5	1.8	24.5 from junction	https://drive.google.com/open?id=1I2DTHA2p6kF5FpTA5he4a7ELT3uRBB-D
35	5.5	1.8	39.5	https://drive.google.com/open?id=1hGhOJtBbjt9F9v61kPwgOB4yn50tVDjP
35	5.5	1.8	42.5	https://drive.google.com/open?id=1-oS3-80ggXxEEDWICASXhqm4LuulOf2G
35	5.5	1.8	30.5 from col s/o 61	https://drive.google.com/open?id=1PLuUqP2LH8LpTEKvR1SD5I7OhxpFIEB
35	5.5	1.8	19.5 from junction	https://drive.google.com/open?id=1ii4Llc4Apx99Lg4IQMY00oHLrjS7PSY0
35	5.5	1.8	39.5	https://drive.google.com/open?id=1FQqbV1TxjPlikYdx6qbcflKkXh0bIW50
35	5.5	1.8	38.5 from col o/s 30	https://drive.google.com/open?id=1BIIOGGC-2x3pUfgAuh8tBMAT1sYS8MK5
35	5.5	1.8	35.5	https://drive.google.com/open?id=1uwclZWb5BfjWcNEyTslhcSeQj2jypToS
35	5.5	No footway 1.8 grass verge	23.5 from junction	https://drive.google.com/open?id=1YH1m1D3KmRqPs0ckdm9dP8UjJEwabyfl
35	5.5	1.8	51.5	https://drive.google.com/open?id=1hYJzAxbuatlh57gwenk5jLITuV9gervX
35	4.8	1.9	19.5 from junction	https://drive.google.com/open?id=1iMYMTWO4CAvpl9Ik096J7tl5EdznEebG
35	4.5	1.8	40.5	https://drive.google.com/open?id=1R4MMHbBASK8F-bo9wQRdYtEq6JlfMgGB
50	4.5	1.8	44.5	https://drive.google.com/open?id=1PsKcW4qFomHZ9FzZCbSkOjvXW1vzEcQ
35	4.5	1.7	17.5 from junction	https://drive.google.com/open?id=1cy6q-M4AqdFDUjXoESYtzJQg_Zxb5fPY
35	4.5	1.7	40.5	https://drive.google.com/open?id=1muXUGjkwDQ8MQUHXj_kh--XZF1V6lz9K
35	4.5	1.7	42.5	https://drive.google.com/open?id=1CwP7xiSzN-e80U4sraq2qJOUtYPd3rR2
50	5.5	1.7	10.0 from junction	https://drive.google.com/open?id=1hXdQaK7paaRUDa7XOf-LPbgW7d_Wpn8T
50	5.5	1.7	35.5	https://drive.google.com/open?id=1T9JWr3X7q8lFnx_gdsi_Hq5j_moRtYBf
50	5.5	1.7	34.5	https://drive.google.com/open?id=1-SlxC9qJ5th7qVB0kwDdr8UXAxyhC1V
50	5.5	1.7	31.5	https://drive.google.com/open?id=1bnmN47ZjV3x8a1GoolU_--MZQ2ezRxl
50	5.5	1.7	34.4	https://drive.google.com/open?id=1ircDH8Eujv_Fx0FpHJXgfyF4enzqZwr-
50	5.5	1.7	29	https://drive.google.com/open?id=1okl8bAxob75F8zjNYjpsYughMqGEyl04
50	5.5	1.7	36	https://drive.google.com/open?id=1Mb6_ACLO3_L39fr5YaMtp7KWICVlPoUo
50	Hammer head	1.8	24	https://drive.google.com/open?id=1UgQFgECOghNgSXXH42k8bKZdGTzSc9bW
50	10	1.8	9 meters from junction	https://drive.google.com/open?id=1fSt2MPW3y1fisFu8-HowL7y_IR9JURrl
50	10	No footway	5 meters from junction	https://drive.google.com/open?id=1VXIq7DRoQ2wlToQ2nYXJhxxeDkDOKRDc
35	5	No footway	46	https://drive.google.com/open?id=1zxoVuICdUN56SKhdRWMC85xpSZc7bca1
35	6	1.8	73.5	https://drive.google.com/open?id=1BtpWL8tRXXGmvHwGcjNEx_l2ZekWtpah
50	5	1.8	19	https://drive.google.com/open?id=1fLWuBqfl-yXz59fwwWBRzUtTcr_MX5wW
50	5	1.8	36.5	https://drive.google.com/open?id=1fCUKUiT0sFs_mQuW_QX5BlqaZD1KZTPC
35	4.5	No footway	30.5	https://drive.google.com/open?id=1GiiOvldulTldVkJXDCQxAXGlpfwtva2U
35	6	No footway	62	https://drive.google.com/open?id=18ipJ8U7hKdR5J0DyoYfneWkt_LxawgXW
35	4.5	1.7	39.0 from junction	https://drive.google.com/open?id=1cDJ4c9hdVKjgD6DaZ9v5YC0QINIEc70i
80	4.5	1.7	43.5	https://drive.google.com/open?id=1Go7zmvnEWdzJl75iyRK-8CrLIs-7x33
80	4.5	1.7	52.5	https://drive.google.com/open?id=1iY8g3VHgLfFlaOHZWsJ_Ajjq6bAF1a1i
35	5	1.7	43.4	https://drive.google.com/open?id=1MfbN7xpZ1yyiHal1gC4dvercgcphsxl
35	5	1.7	48.5	https://drive.google.com/open?id=1PIQqigZ7op-MUjDUGEEX5k6hzKGfnDC
35	5	1.7	50.5	https://drive.google.com/open?id=1a3de19BF_YJ3Sy9jGS1qJ5xig3Jnn2XX
80	5	1.7	45	https://drive.google.com/open?id=1_lxDOPBLz6zkY-0aHfhVr9j8AAbuP2sn
35	5	1.7	51	https://drive.google.com/open?id=1fkPTsA-erwVS8SGkaMf7M0CIMNbeU9Rs
35	5	1.7	52.5	https://drive.google.com/open?id=1adavfEgyYh0VeNjGESRxDnBgmEKTEZSC
80	5	Set back on driveway 9.0	34.5	https://drive.google.com/open?id=1Bi-M4PmD1NSe-r-01810oY_HftZYDU
80	5	1.7	48.5	https://drive.google.com/open?id=1IA4WpVpityPijhBhWpyMXAmWDdzyY90N
80	5	1.7	14 meters from junction	https://drive.google.com/open?id=1uGud0fHARK21R6SKbiMqSfFRpqtMeaxy

wattage	Road width	Footway width	Spacing	picture 3
35	Hammerhead	1.7	50.5	https://drive.google.com/open?id=18CkGkFJswLp0e4Wiz2hHozhgnsWzGjaJ
35	5	1.7	46.5	https://drive.google.com/open?id=1Jp9J_ViTI_1mI0PxmFfLHvxjU-2rTMj
35	Hammer head	1.1	35 meters from junctin	https://drive.google.com/open?id=1bV8Sfgx1r5Lvx6Sv9amZVVqbzsMeWqil
35	5	1.7	33.5	https://drive.google.com/open?id=1vPnimzuMYrFhgU3NDv24hyapP0_rZHP2
35	5	1.9	37	https://drive.google.com/open?id=1sihm2GGllwazB39-tU6T_xmhZ--u-sgE
35	6	No footway	49.5	https://drive.google.com/open?id=10shjfMFsjOaQSiQ_ABXalh7omryRqvUu
55	6	No footway	24 meters from junction	https://drive.google.com/open?id=1cAnpsjsJd1E-NKvfj9yTkkRkKlnYk02Z
35	Hammer head	1.3	46	https://drive.google.com/open?id=1gknr9hPx9CLTkoGuAluCGX9l64pgyKAI
50	No road	1.5	1st column	https://drive.google.com/open?id=1aTbHoE7oc2FQx-LznQDeel9sfu2dNdbW
50	No road	2	38	https://drive.google.com/open?id=1vfBlrxZ_QEjIwZ5UoKVocjTO-oZ88K_v
80	5	No footway	1st column	https://drive.google.com/open?id=1gJK5TlOjCihxNbGp2Rf7q3TnkRube7LZ
80	Hammer head	1.8	47.5	https://drive.google.com/open?id=1hnOmsuuYjhx2LSfKBmhJcchE3cDgmv6e
80	Hammer head	1.8	49.5 from junction	https://drive.google.com/open?id=1cV9PQ6Ntav1NMmYAqnxRPSsdFrgDomDJ
80	6	1.8	23 meters from junction	https://drive.google.com/open?id=1igvP8os8cm4jb05Rp94z4nu8cl6rguBj
15	6	1.8	43.5	https://drive.google.com/open?id=17mApM0NbD8r4CTz6LsUbkltkCChdYAbd
50	5	1.8	22 meters from junction	https://drive.google.com/open?id=1JK5ReODTvvJGiVRfeaBdPXcguhYLILDR
80	5.0 opp cul de sac 2	No footway	48.5	https://drive.google.com/open?id=1arkZ4vN_WEQHuNMV_wzCkfrbIBRsMwn
80	Hammer head	1.8	55.5 meters from junction	https://drive.google.com/open?id=1M4noj8gpYVc1uiyvIcqqzo8DnWjM5Egi
15	5	1.8	36.5	https://drive.google.com/open?id=1UzW8yd42vJOi059dRPMYYpdiUOJQHrME
80	5	1.7	36.5	https://drive.google.com/open?id=1kLXVxemVzLNgFoTN0cymwE47MLhIO26h
80	Hammer head	1.8	45.5	https://drive.google.com/open?id=1imBuUcKFAMFig4trbfGFJa3CusaJMp_v
35	5.25	1.8	17.5 from junction	https://drive.google.com/open?id=1ELUAV8EcwYb0NOPmZjpPmD5jtNMTRXHi
35	6.25	1.8	46.5	https://drive.google.com/open?id=13jilEngsQCXw7OpSjyt_c8_EsJyd9wm
35	5.5	1.8	35.5	https://drive.google.com/open?id=1c1IPNAvbtSfvw3vXrL5lBm53fVkpWp2
80	Hammerhead	1.8	50.5 from junction	https://drive.google.com/open?id=1r3EnngmU_2v3n4HS_c6H9ZurDOXwHKsP
35	4	1.1	38.5 from junction	https://drive.google.com/open?id=1YsGBCfUmcHKJHIT4uFUMUtg_RyAv33H
35	5.5	1.8	24.5 from junction	https://drive.google.com/open?id=1Vr_n1Rtyhs6z7Z6icUBnWyyJx9Mu0ABb
35	5.5	1.8	55.5	https://drive.google.com/open?id=1sRh2OtlGluBLl9kknUblVvshQRgXLSt
35	5.5	1.8	34.5	https://drive.google.com/open?id=1EODp9ZbpXW4_oYXk9l5cUoXy8l-vKW3n
35	5.5	1.8	55	https://drive.google.com/open?id=1IS_vS7LR_G-eqSg7roaRztHmydydCzUs
35	5.5	1.8	43.5	https://drive.google.com/open?id=1jEygtQ8rIR3dgu8j1J4-h8h-NM7BYUkJ
35	5.5	1.8	26.0 from junction	https://drive.google.com/open?id=1WTqwgCb-jN0udTu7GfUCA_FcsX7UbK5W
35	5.5	1.8	55	https://drive.google.com/open?id=14UfQcj2plhrvmbwvLrMFZbsbpwsW
35	5.5	1.8	47	https://drive.google.com/open?id=1fk3eWctiRbpKdM_3lk11XmBmGKy0m8jx
35	Hammer head	1.8	39.5 fto junction	https://drive.google.com/open?id=1pYTtOpB7tiqprnvMfifUq1-9YiHbag
35	5.5 hammer head	1.8	40 mters from junction	https://drive.google.com/open?id=1PYg5H8mGijMCO894b70uD0K0Wp4E8v3r
35	No road	2.8	69.5 from garages	https://drive.google.com/open?id=1D4oVApOGwiVcaGu70R61xCTs4xLDi5_u
50	No road	2	73.6	https://drive.google.com/open?id=188Lm8MFdasnlUAyxvzvbg-xuZXZEBvOr
80	No road	1.2	19.0 from road	https://drive.google.com/open?id=1eZk1ze2rSDm4O87fGfPCRZCGSmywf2bD
35	No road	1.2	34	https://drive.google.com/open?id=1kmYg16DdlYhGN0ICNOElrKA0FHRnr8sn
35	5.25	1.8	8.5 meters from junction	https://drive.google.com/open?id=1AYSQLOYWleRHL5jyB65mz8gSDj0hsW0
35	5.25	1.8	53	https://drive.google.com/open?id=1pHhnanmABs-tzn1xP39eWlwn7Mr2rfMB
35	5.5 hammer head	1.8	52.5	https://drive.google.com/open?id=1ULMF-G2UrU8qjJ5lqAvM0jDKMezZ3LOE
35	5.5	1.8	47	https://drive.google.com/open?id=1_uwh9slu832YUBy6E4jJCdyAMZOITr
35	5.5	1.8	17.5 from junction	https://drive.google.com/open?id=1k9M0XNXqWR01Z1ofJ74y0TgFKUV-bpnm
80	5	No footway	33	https://drive.google.com/open?id=1keOUoTaMpBdevhFSMhk_gB8QDVAMPo_t
80	5	No footway	67	https://drive.google.com/open?id=1VQxVbf-V_Rd0uXlpP2tIF-Q28PcCveKA
35	3	No footway	26.0 from road	https://drive.google.com/open?id=1bGiP18V27PqjJOA9Ts34RfkpUF7Pjxt
35	No road	2	33	https://drive.google.com/open?id=1yHf2-SUK_fJyBN7WfBCE2coR--sfBy8s
35	No road	2	32	https://drive.google.com/open?id=1IKd1ipKqC0oKPxrFAuegeZ5qAN58LjhV
35	No road	2	38	https://drive.google.com/open?id=1Ht7gHawjSy5nY5AglETV2cH7Or5ljaEZ
35	No road	2	17.0 from road	https://drive.google.com/open?id=1xgbuvrdqsP4gHmjQgB13wOIFjyy5VhDu
35	No road	2	31	https://drive.google.com/open?id=1SwFFTnkPFF20YNOM7m-PBbjmkIOk-Xnh
35	No road	2	30	https://drive.google.com/open?id=1eLl0ZWuw6EODp47c7dXkQ9gS_IHm1-O5
50	No road	1.2	42.5	https://drive.google.com/open?id=1eR3tHnOYwL0xL9sV3lplz6TD6WgMAQ8
35	No road	1.2	20	https://drive.google.com/open?id=1txisPmE6YVEstCHHt73DSP1iy8BimK8n
50	No road	1.5	19	https://drive.google.com/open?id=1-n4N8Z_yoliXtN7jV-tDJYpXFN2j9RIF

wattage	Road width	Footway width	Spacing	picture 3
70	5.75	1.7	8 meters from junction	https://drive.google.com/open?id=1AIWx5j76pNlftS3hjdW9016EDV6P-EJ6
70	5.75	Q.7	32	https://drive.google.com/open?id=1shdpAwwD4Btf1Woe39yQaKYkRJaJGmDE
70	6	1	@8.5	https://drive.google.com/open?id=1Au_44ufRlulhLxz5JjM7If6le3YC_Uae
15	4	No footway	32.5	https://drive.google.com/open?id=1siz8LOIZM1W7upNnG88rRz_BVhw4_D4
70	3.75	No footway	28	https://drive.google.com/open?id=1vCxnGQ-3d9E0NneAmQhn_7h5fugQfpC-
70	4.75	No footway	34.5	https://drive.google.com/open?id=1Wd7rnAA12HEhNLBm2pPQ0DJSh7JkF9A
70	3.75	No footway	20	https://drive.google.com/open?id=1i83DGdnM9_uGXl3OuEgY4mFbUogdBwu9
70	3.75	No footway	31	https://drive.google.com/open?id=163pvtwuBFci-YiIRJF29-rc2uusZcclT
70	No road	4	In courtyard	https://drive.google.com/open?id=19V6KnSDuVQOBtcwDN_rLM0YwwWDKT-GD
70	No road	Courtyard	21	https://drive.google.com/open?id=1v8qeAUNsS9Ib1eNzeL2HlL4a1skthTF
70	No road courtyard	Courtyard	Courtyard	https://drive.google.com/open?id=14DVnjdwS_dNOs2iGqORAWvf5kaU-ikQz
70	Courtyard	Courtyard	Courtyard	https://drive.google.com/open?id=1HH-B4hysII-XTEYbqg0hf3WLAZS27S2N
80	No road	2.5	1st bolard	https://drive.google.com/open?id=1xU8b4ZNB9bTBxWxc-WnwKGS0gEq3jZQy
80	1 meter high footway bollard	3	11	https://drive.google.com/open?id=1UalXdqUiSRszYAHp-YXV1LHzkQm1fsLA
80	No rd	2	7	https://drive.google.com/open?id=15wZkimAeYEnhwivdJ3LDi-J5VBYpDQri
80	No road	2	6	https://drive.google.com/open?id=1-JloOfWkqZpvLiKA9NxmVUmB_XNF6mbZ
80	No road	2	6	https://drive.google.com/open?id=1SxSl_4aXUeYDBW1myWuZe7eixKb49Ld

Road Name	Supply type	Column number	Picture 1	Picture 2
Red Bank	DNO	No number o/s 58	https://drive.google.com/open?id=1DwOIEw2u0YEI55yE7L06yloDhLM6Kw0G	https://drive.google.com/oc
Red Bank Cul De Sac	DNO	No number s/o 7	https://drive.google.com/open?id=1sFVylKObSEAdYfcpXn9ZMv5s0N41jPM	https://drive.google.com/oc
Red Bank	DNO	No number s/o 52	https://drive.google.com/open?id=1BgtR3ClpJbRCYoD0YZnqaVTnew6l0r46	https://drive.google.com/oc
Red Bank cul de sac 2	Dno	No number o/s 50- 52	https://drive.google.com/open?id=1fagPdaERAI97sV5ntmSoXDYtXdnCs430	https://drive.google.com/oc
Red Bank cul de sac 2	DNO	No column number o/s 14- 16	https://drive.google.com/open?id=1iyKwkNjeT8o4d47rPFVtxvjvYKn3f67	https://drive.google.com/oc
Red Bank cul de sac 2	DNO	No number s/o 30	https://drive.google.com/open?id=1Vkl2sOVJISDOcKrlVxn8e8uObtYKZTdl	https://drive.google.com/oc
Walkmill road	DNO	No number opp kilnbank road	https://drive.google.com/open?id=1i4eqSwAn4mDfnoySiFyCh-pBzp6pnk8h	https://drive.google.com/oc
Walkmill Road	DNO	No number o/s 80- 82	https://drive.google.com/open?id=12XyLeiwzV9VfDtBnATJ0Bu24oz51uhMP	https://drive.google.com/oc
Walkmill Road	DNO	No number o/s 72- 74	https://drive.google.com/open?id=1kuy_4m7lw-xvQKcBfsCQkLwOJH70Mcdb	https://drive.google.com/oc
Walkmill Road	DNO	No number o/s 64- 66	https://drive.google.com/open?id=1B4F10vmT5grAzfFBwosbf522PCHG0O1k	https://drive.google.com/oc
Walkmill Road	DNO	No number o/s 52-54	https://drive.google.com/open?id=1fLjyotO3k9zN9wwwDFwmdPEYtJH_LlyC	https://drive.google.com/oc
Walkmill Road	DNO	No number o/s 42 - 44	https://drive.google.com/open?id=1PllcBfVtiWbRUeUixpATdUtNjq5OWAxo	https://drive.google.com/oc
Walkmill Road	DNO	No number opp waklmill drive	https://drive.google.com/open?id=1sF9dYr0PqVAgn6MvxLygz8rJRpIKBei8	https://drive.google.com/oc
Walkmill Road	DNO	No number	https://drive.google.com/open?id=1WaWtQHQQqBOK4fRr40DYUwYySPJx6tnY	https://drive.google.com/oc
Walkmill Road	DNO	No number opp 27 the hollies	https://drive.google.com/open?id=1Sr5jyVMY9UBQ8WOHOMarX0dJzi41ZUP8	https://drive.google.com/oc
The Mount	DNO	No number 58 mtrs from Walkmill	https://drive.google.com/open?id=1Za0z_q92fsQ2pso9HMbwHpnmkrvNJ9on	https://drive.google.com/oc
The Mount	DNO	No number	https://drive.google.com/open?id=1CMKydQ_DmBSzyZ6_EUssrTOicGcwJNW0	https://drive.google.com/oc
The Mount	DNO	No column number	https://drive.google.com/open?id=1vPASu3MBmEUysoMnjgn9_fxlGLJPnZ2r	https://drive.google.com/oc
The Mount	DNO	No number	https://drive.google.com/open?id=1hZveHhFjsz7OR53c7U8eNV6PIFYQV_PF	https://drive.google.com/oc
The Mount	DNO	No number o/s 3	https://drive.google.com/open?id=1lu5tpWjchtKh67Q7KpfCBLLrZ7EJH1xc6	https://drive.google.com/oc
Summerhill Gardens	DNO	No number o/s 1	https://drive.google.com/open?id=14z11VPbr_-XiJHocv3fhdiARYftkBZ4	https://drive.google.com/oc
Summerhill Gardens	DNO	No number o/s 36	https://drive.google.com/open?id=1Cwg0MqOJN1QbeB9EJ9WynPELatnF05HB	https://drive.google.com/oc
Summerhill Gardens	DNO	No number o/s 32	https://drive.google.com/open?id=1KRw50rmB-QmRPv9avYvl0WVcMTOXYVM	https://drive.google.com/oc
Summerhill Gardens cul de sac 1	DNO	No number o/s 31	https://drive.google.com/open?id=1ieiixVIYBAsVD0v078QIXQc9818MXWd	https://drive.google.com/oc
Summerhill Gardens	DNO	No number o/s 24	https://drive.google.com/open?id=1fHB3DWU3AgExfnWzcnFnaAVQ4NzXaQs4	https://drive.google.com/oc
Summerhill Gardens loop cul de sac	DNO	No number o/s 13	https://drive.google.com/open?id=1zc_4qgo-8fXatMBq-ec9AFR3v5MxOE-C	https://drive.google.com/oc
Summerhill Gardens loop cul de sac	DNO	No number o/s 20	https://drive.google.com/open?id=1-l6KWv5gzkFUPma8iRIOCiftrp4dAIBl	https://drive.google.com/oc
Salisbury Hill Veiw	DNO	No number o/s 65	https://drive.google.com/open?id=1eLY4fxgMZtbj4d47htRP9NIXuYl6fZY	https://drive.google.com/oc
Red Bank Lane footway	DNO	No number o/s 8	https://drive.google.com/open?id=1Nbi6dZM9mK4Jk_kadUa_rGm_SXBqzwoL	https://drive.google.com/oc
Red Bank lane footway	DNO	No number 24.5 meters from first column	https://drive.google.com/open?id=1MC1quYh7NhyFSMo_wnX0jrn1YyO2w9B	https://drive.google.com/oc
Red Bank lane footway	DNO	No number rear 57 23 mtrs from road	https://drive.google.com/open?id=1YQnlbFUFOaN- L_CAEIYPVpQQ4TsZyED	https://drive.google.com/oc
Red Bank lane footway	DNO	No number	https://drive.google.com/open?id=1tuunalwxLeMzrynHgM6xZUOmRz0kaOqyY	https://drive.google.com/oc
Red Bank Lane footway	DNO	No number 57 meters from privious column	https://drive.google.com/open?id=1Nim2l8Uzvbws-n9cqqbDZzky9tdVTSiv	https://drive.google.com/oc
Sutton Way footpath	DNO	No number s/o 7	https://drive.google.com/open?id=111ArYp_lm76uMdtVWpRdKPx-Ax6o2JW	https://drive.google.com/oc
Tern View	Dno	No number o/s 10- 12	https://drive.google.com/open?id=16wzqlyweKkKQ0J-2q8anXr09KgR00YH	https://drive.google.com/oc
Tern View	DNO	No number opp 16	https://drive.google.com/open?id=1uwDLNBgJ95BlfXgl8sbwrfEVQ2mooLk	https://drive.google.com/oc
Tern View	DNO	No number opp 27	https://drive.google.com/open?id=1AMGKOITgdE2iNatLgKci9MEiRtvlICm	https://drive.google.com/oc
Tern View	DNO	No number o/s 26- 28	https://drive.google.com/open?id=1xbE6C1Gx13d-xiqulhgJURDo6kTbGTtr	https://drive.google.com/oc
Tern View	DNO	No number o/ s 2	https://drive.google.com/open?id=12D4OKvZIJWWOqO9ux1Lbi5OYnybWlaS7	https://drive.google.com/oc
Newtown	DNO	No number opp Bryn	https://drive.google.com/open?id=1fRRKjM9P41M_54FOkcjaHmwkKolLHXgD	https://drive.google.com/oc
Newtown	DNO	No number opp 4	https://drive.google.com/open?id=1fVWShaEw1ng206iuzcROG2bYaMWFfMnT	https://drive.google.com/oc
Newtown	DNO	407 opp morningside	https://drive.google.com/open?id=1W937N3uzmYtJz3nxjryArDdXuRR6B6T5	https://drive.google.com/oc
Newton	DNO	No number junc dog kennel lane	https://drive.google.com/open?id=1I_A0hmlqwpBm8WzFnFVAyy_eVW7XF-sN	https://drive.google.com/oc
Glendon close	DNO	Col 1 os 1	https://drive.google.com/open?id=1fKsVbbkVl4P3wgVzsrV1bgqjrrthUuEF	https://drive.google.com/oc
Glendon close	DNO	2 o/s 5	https://drive.google.com/open?id=13wlGk7uRQgHzN4oUFzZBHEvfh6RtJ8j	https://drive.google.com/oc
Glendon close	DNO	3 o/s 11	https://drive.google.com/open?id=1AF9A_V5P_XbUfNR5v7WAlcBCWtmnj31	https://drive.google.com/oc
Quorn Grove	DNO	No number o/s 10	https://drive.google.com/open?id=16ttJf2a4wCRZ9yuF9KEiuA69uMEzau3u	https://drive.google.com/oc
School Lane	DNO	No number o/ 12a lavenda cottage	https://drive.google.com/open?id=1_W5kNuijAstJvDnG7zldOZIKPQdmvde	https://drive.google.com/oc
School Lane	DNO	No number o/s kinvara	https://drive.google.com/open?id=1RnNHfSHX1AnciRsotnC6nKL_xqfk70sl	https://drive.google.com/oc
The Burgage	DNO	No number o/s 11	https://drive.google.com/open?id=1ncsPp2ZUDdBDmitW9xiJkqgZtOzXh3c	https://drive.google.com/oc
The Burgage	DNO	No number o/s 28	https://drive.google.com/open?id=1m0mI56VeIARRN6heHWR4A9vp6oJLOrf4	https://drive.google.com/oc
Burgage Close	DNO	No number0/s 2	https://drive.google.com/open?id=1I3tdxXhA6MWRdXmMydEiLixGPZ8nbvqf	https://drive.google.com/oc
Burgage Close	DNO	No number o/s 7	https://drive.google.com/open?id=1qJ6QvzfQGIs1M0i6cXwSdvEiffRP3Q7F4	https://drive.google.com/oc
Hinsley mill Lane	DNO	No number 0/s 3 kirbymore	https://drive.google.com/open?id=1tFqGq7ql3AXU82HqcLwnjdBI9b1k-Mcn	https://drive.google.com/oc
Charter Court	DNO	No number 0/s 27 opp 2	https://drive.google.com/open?id=1FKRpkbDCtPLe1t1IVJgmfNhtIndPxSB	https://drive.google.com/oc
Charter Court	DNO	No number o/ s 4 hammer head	https://drive.google.com/open?id=1IHrnvD6MTV072foW7A-ftZfibe1lwaq8	https://drive.google.com/oc
Charter Court	DNO	No number o/s 22	https://drive.google.com/open?id=1hnKh-AZnygKsXTEYin-pd1rJ9iz2ckXk	https://drive.google.com/oc

Road Name	Supply type	Column number	Picture 1	Picture 2
Grosvenor Road	DNO	No number 8 meters from junction	https://drive.google.com/open?id=1clSdiz33epqC9T2qOek6TcoP8e1MpAs9	https://drive.google.com/open?id=1clSdiz33epqC9T2qOek6TcoP8e1MpAs9
Grosvenor Road	DNO	No number o/s 1	https://drive.google.com/open?id=1k6nvbshL70ZG4yOmo6ZrpeIV0_838kEE	https://drive.google.com/open?id=1k6nvbshL70ZG4yOmo6ZrpeIV0_838kEE
Grosvenor Road	DNO	No number o/s 15- 17	https://drive.google.com/open?id=1RrMoiKDcakqPyt-9NoFBHISs0ezsNMyV	https://drive.google.com/open?id=1RrMoiKDcakqPyt-9NoFBHISs0ezsNMyV
Grosvenor Road	DNO	No number o/s 21	https://drive.google.com/open?id=1nZ4XZa_HL4awCrKpPIellfAtNW9FRiml	https://drive.google.com/open?id=1nZ4XZa_HL4awCrKpPIellfAtNW9FRiml
Grosvenor Road	DNO	No number o/s 32	https://drive.google.com/open?id=1ULyDJB480p4VcK4U4hMH4cJB_GrTeoDoG	https://drive.google.com/open?id=1ULyDJB480p4VcK4U4hMH4cJB_GrTeoDoG
Grosvenor Road	DNO	No number o/s 36	https://drive.google.com/open?id=1nTbXZtaicQwh-Q7U64TJf7QagvwUaH8X	https://drive.google.com/open?id=1nTbXZtaicQwh-Q7U64TJf7QagvwUaH8X
Grosvenor Road	DNO	No number opp farnfield	https://drive.google.com/open?id=1hdneXZDayt-6nLk78XZ6UJ6Fg6f9nSF5	https://drive.google.com/open?id=1hdneXZDayt-6nLk78XZ6UJ6Fg6f9nSF5
Grosvenor Road	DNO	No number opp the laurels	https://drive.google.com/open?id=1ZX0I7clY93_Dk14rvOJnAF2WZVKZo7pK	https://drive.google.com/open?id=1ZX0I7clY93_Dk14rvOJnAF2WZVKZo7pK
Normanbrook Court	DNO		1 https://drive.google.com/open?id=1SqoeiPq54WW6pOdISV-plu7wONLLLeL9E	https://drive.google.com/open?id=1SqoeiPq54WW6pOdISV-plu7wONLLLeL9E
Normanbrook Court	DNO		2 https://drive.google.com/open?id=10Mp-8laTKkTeEOf9OpBFhw6zNgelQ-yC	https://drive.google.com/open?id=10Mp-8laTKkTeEOf9OpBFhw6zNgelQ-yC
Normanbrook zCourt	DNO		3 https://drive.google.com/open?id=1MxJiNkXI1P3Lnt9bNP3ad-9uXp3PxZkc	https://drive.google.com/open?id=1MxJiNkXI1P3Lnt9bNP3ad-9uXp3PxZkc
Normanbrook Court	DNO		4 https://drive.google.com/open?id=1vU4VyDzhc45KiAjw1k8TSF34TMnpTrtF	https://drive.google.com/open?id=1vU4VyDzhc45KiAjw1k8TSF34TMnpTrtF
Normanbrook Court	No known	No number o/s 9	https://drive.google.com/open?id=1v2hy3YSOdkKPRBezPzJza1b02kX-tCUL	https://drive.google.com/open?id=1v2hy3YSOdkKPRBezPzJza1b02kX-tCUL
Normanbrook Court	No known	No number o/s 8	https://drive.google.com/open?id=11tlHkBE2Ncg0_YBlvg4GBhYuzik16X62	https://drive.google.com/open?id=11tlHkBE2Ncg0_YBlvg4GBhYuzik16X62
Normanbrook Court	No known	O/s 7	https://drive.google.com/open?id=1xTwBjhqVIIEqD21-Z98QHfX3GMXVKzZ	https://drive.google.com/open?id=1xTwBjhqVIIEqD21-Z98QHfX3GMXVKzZ
Normanbrook Court	No known	No number o/s 5	https://drive.google.com/open?id=1Zml5-EJ9n5UDDKiHH5GFv6Jez5ECaxN1	https://drive.google.com/open?id=1Zml5-EJ9n5UDDKiHH5GFv6Jez5ECaxN1
Normanbrook Court	No known	No number o/s 4	https://drive.google.com/open?id=1bq3E2VLtgwLE6Z4lpwFEURC2bRb7NeB	https://drive.google.com/open?id=1bq3E2VLtgwLE6Z4lpwFEURC2bRb7NeB

?id=1oBQ_iThDCIJ5fAW2RU-viv5jJBVeU3ZW	
?id=1Wff0p-VyLoxt9foXEdWAhC7QhYoB1J8N	
?id=1PMdZkqU3duAulH14PPLJZozDDA46icKl	
https://drive.google.com/open?id=1jGuXn-IHamuwZ	https://drive.google.com/open?id=17Pr_5hkdlAWsKSDqeH7BkAGhnC4d8hu
?id=1XduZ4p9QGAY45WYIKFYQOj1Ux6bfwa4	
?id=1Q87ZhhLDss2zYZPM3VXTOAW4uTZbf7ZP	
?id=1TxVrLJdcsiROAR1Tk-C7FE3AFc6oPc5l	
?id=1moD9wdKIG54a-b7UiuJ2Qn4vYNt7WZnd	
?id=1fMrkC9ITdf9l_CR41AjK-08RNK0CFty2	
?id=1NZ7h8AdaPpX1RDC7aC3CqATupf6M1eRp	
?id=1LxIzhKjyZKm1A9RVWSP2kveoedVcQpi	
?id=1Y6h_z3zeBSw7yMnADwpdzsvFEs9Nel0i	
?id=1I2KUBXVxqZ3SEzbuyecxosX_LZT-YdeS	
?id=1VyYlgbSRy6AOfrieXlbnCbXMwqom46	
?id=1GyACfQRFzyUAsq4WQHcXJM6ZybKeKvlt	
?id=1sBTTRAp9nzFZGPhnSpzUC7H7am_bSsdH	
?id=1LQxjVrM3bM4ZG_OtySedY_rtdi6F4kvf	
?id=1XE3OCSJIWupeXemMWTfiYb9m9yPsnZvE	
?id=1mOjzPXXHxGSsyYq8OT83icy8LoKg5Y	
?id=17txNLIHEI7xJ5CdLBX5xd8CCplug-fTV	
?id=1CFOGR12aJJUXZrVJSQ5CBcXsLjHGoiKK	
?id=1100kyNj6Aq3yfDRqsS--DSf3eLN41jWo	
?id=18tbbLKyunH0E8nOpzZNRqCAKQ5TPFnQX	
?id=1DGg9BA3BT6AP-nhnNOpa8QrtLLGQ	
?id=17wXAWSHWn2J7FBZ_cXdMILGs8-ZkQU-z	
?id=1LvkUwfrS0FdBipWUUiinM4Csa-Yqq26T	
?id=1GyxVZSsPC1dvx94YJCvIhlcS3Nf1vwh	
?id=1jpvVweXvB_DxFce2WqX3cT0Er6hsJb3J	
?id=1w0WpJMW_vDe2E9MjBXsTCIjHAxtV1XSt	
?id=11Lx3s2lcQDtjS2PmBlid9QycMWgo8f3Jj	
?id=1_7FsgTFcR95boSMYtsXn8_n9y6DDjdOq	
?id=1v2CwslqA_g7esayamW1Ei4_4iXPjNksG	
?id=1S7zNHFI3IziOjWdAjsVjos4ZmriBKM2b	
?id=1-GdtgdDTs7oJQFE15RhQdEDRKP3pSSw	
?id=1AhD7B8XAnX4Bu6egmOc136j45t4TehQg	
?id=1aQ9ArnPIRahp3S4b6RlthyYbh9olsLcY	
?id=1gkaXziGszDtFfXMDyIUayUwFtBlNaABc	
?id=1r-EVSVyqWa0vuREaVT9fuLS0rk6VFkvF	
?id=10JjqJrrBMkrhd0xH8huWMchml7CRi76l	
?id=1gx2sQHbBDbnVbPbBsFOCteqxnU2V11b2	
?id=1yezFypXbw1BT99ilG73F8hzRQDtu8APX	
?id=1w9rJfE1KbVjNPBEHPxE4snp4JVzbEmv	
?id=1F_e04coi5vTr6DEf_L2TJtN-9LiHeTSR	
?id=1RutzBS8yB1leS2KyDwz_j_eelNaPSG9N	
?id=1Vm_P5G2lfR1nWLQfZB2ZZiQIXDBCfk5M	
?id=182mSTI5DOoqNTp97ftRZ4-U7yWi7PRPc	
?id=1g8tgxBz3EDmQFpTqoOcozVTeTihK2fa-	
?id=16Jb3RmB53NmYpaaPpRg7Jh4FHfEAmyp	
?id=1Yp5LJbu0Ersow9nfyWvVVNnZmsU4mzk0	
?id=11WhsW_yZY1oqLTY9xwPrubetUPRx8o2d	
?id=1WinLD5_4kgG1CTrIjDnc1Sv0OcFNdKVl	
?id=1cirRgBtYTC9dESjsfOhlg9JydlvUI9Ge	
?id=1FFYJpexdkdGMT1AZII45OKDtizi0qPQP	
?id=105fHkrExwHLqSxWF62oJzXyu3QqNIDQ	

?id=1QAC8KIn86C7jWzUYj60nBKgQIm5zUq2F
?id=14yme6jlrkrtXWlmgVn8xS9u-hO8_C5Jx
?id=1Drn01SQ2b43bmfDWvVGBi5z3OhXV2-at
?id=1GWXZMtnDBEwY-W6oGJ0DN2p_KLerx-aZ
?id=172-7Ves-omB_of9-NDv7EWAaDg4iyVPN
?id=1F_40K1Jgf8aszR0Jum3CT4p6Nr8cSMr5
?id=1a91yk11Zp_KxJ8xNk89aEsoRMRkcEmk
?id=17viwUAg9WFeXSuo-gadqKlaaygEfAoNT
?id=11s-nW5XERd6BcjiW-XUwJebYu13Q6cRI
?id=1ZZi11BFjzL_Th5F7zWjgmgOYDxmZSng
?id=1Gm2gkvENr89yQI7f6Cfkr9CMViCLWD66
?id=1BTNiH-WTCJ5ZhRmW_a3M1ydZDPbWIGXL
?id=1qTYuzylJb7LjP3TFC2aTiLLcgkZPqQQj
?id=1CTiS42E1FhfWmfFQ9jMWxzSDhgB7cd0E
?id=1hoplGR7Z-gY927rOcEqEd0p-INIIR3j-
?id=1solE23dWQMUNwj8sDMyohZMMWGXacyiU
?id=1PEQg1tIPoL2qzIVie06LqfTgLnL3DRA
?id=1ZQ7ha2yURj-ICHy06Cz5TpK4PuYNDkcr
?id=1JKjs9P2O_LVmV9Lc8ozBAz41LTZGkhBn
?id=1bv5tRRDZyQniaQtQ4W9arjrkAVzCViv2
?id=1u4Z5WnlRqOYJuV65Fo4RkQP-OoQFyaqJ
?id=15jA666uE0y7cCVdBV3y7IzcBwGwzalH2
?id=1UDCnVpTQZL6ug_G8xJ9rAJrLkVlo07Z
?id=14cYPUG5g25dm80dHcQQOfKZnp7aNg55m
?id=1EpDy0PVyQtC6kRQTEntfS_UxwRLUBZh1
?id=18lxpphw8tfkZS2hS37XiPFD5eyLqL5sv
?id=1ciBxwK0t7HfjBw66jL2PjKS9UZg0jJ4l
?id=1i_ZETrkK36Z3aPUGl_RGeoxsJu3ndGkT
?id=1vHrqb_zrX8NHvcY1UKsNjGMe75JDrNxy
?id=1jOq6szrwwOHicjEc312Ji7wT_zssjpkN
?id=1jV-p65qYfKrEW8xogc6TmA2L7mHog4l1
?id=1ctxSqZvNuyUTTU6g7iXkBednN99M28uK
?id=1fzFw-iGs-AFEoaZ3pb-JYmBTTVDQ3CXc
?id=1kR4GY9XXixLbRSulgVUCy1Hk51flqXQ
?id=1lau3RQ7I939MH-ZNAFyjiAl2d9Y53RAQ
?id=12a_AalZq5PSdkgWIAWsfq-0xaIWoxBEem
?id=1pnUC3ai_R9n3kKt4RBmVfJkM2tAbhPz
?id=1hs3WRv2w7NAfTC4mEHMnMXAofpfssrf4
?id=1iZt5z3foSr2gQUibrVBHCxiGR491O0Bo
?id=1Kb2kv0VYndcjsidDXa42rRaidNjz_Nc4
?id=16JuXtPkM8pZa0QmqNyKDveVhnM07fsAG
?id=165x46kByU55OA61-UrEV_Efmd52bfbm0
?id=1hpgBHm_4h4gpy768JZ8XcGARim52_4fl
?id=1yVzqnnOX4nFSAz7ZvidO53ocplpGZ2DV
?id=1zRGbhGHE49BYLPfTt_7F8md2Yv_utNuO
?id=16JqfOd71P2Bna1luAxlj_XzzZth1Fyep
?id=1IIO5ciHltdeXsjJzN15Q1nZkxUfoSFnp
?id=1EveSW8GQWQQnk2a8-XCIAUy-T1-GcxEe
?id=1w0jhRUBD6WoOViHEUPPsh9rKnfNpuFMI
?id=1JSh0saAJychOZDRTAKn8U5Z6-ewsDAX-
?id=1vWCjD5FI9hXxKhN6DEbscijacjtDQ-c
?id=1mRNitLo9YgixXN_CI_YL_4lbpLBJt5Aw
?id=1wlv744Lwsyyf9z5p-KKzVOGIIIBXvDnv
?id=1UgCmwzq4fbXvHvl83mwzP023JQTTT8m6
?id=1lqn_YAQyGxD7AZjvJT02rVqgwrISUm0z
?id=10WKJ8_w-ArY3XfPXubcVmntw8hShWD5Z
?id=1Pfw7WhDoAuk9nTNKNJp5xcNHwf_WyTi

?id=1pUEUVGXgpht1RrmcBW57kONZB2ebA4v7
?id=1- FmGFeS6i9L12d mO-o4-vExGvS6UQx
?id=1UCvtOrGUXXWhcjeryNXk36wxJOg8L-9n
?id=1tbR9EJVnYlxFV4SXRm61vGlnHf8gN8oe
?id=1wQlaAV2oCABRiP0C8P2LJA X0DvjcmQS
?id=1sVAVIzFlsqJwK2p7O0eSCM6gTkLfIEQE
?id=17FC7VjI6Jl1YLIZJjDH8ZFsaVn2GgUE
?id=1j2T1M7-gfghpVJP9jFFdNx MOQa0iWAo
?id=1SpUnd3vVLOha8johei5qcv9wMqm7-KQP
?id=1rDoLD57Ek1cNt3CAxjci-bvMJ-CrhS2g
?id=1GpsDBG0I4BT7O9NPBSagg34KKOW CZOb
?id=1XWIX096pWERz2dhVyoPfkKoVeRUCfROq
?id=1mZidIM rrz4CzosPKceWR5DwRWBCllsX
?id=1KhW9uotifzNv8HDfhMktRYwJ5X2ReX0
?id=1ff1c3wfrSq2LE1YQpGfrle-1sn9gLpKg
?id=1nFRDgOBgOegBP3mCTCijLOL66arYNaOn
?id=1gviPaRdt5Mif404sjveZ0 4QTKRpO0t
?id=1c4-jAAjUjrCZQrx6aZm0oplUbjuvBCGF
?id=1YrRfPfk 4tYgN0oNnfRE3tSncr5rShVg
?id=1CjqZJwkrREjL0cmV4Tvxspb7dGT6X8xf
?id=1ljhu t8D-zskTzC74RhV79KMKgjlLg
?id=185b1eYMUUIXzwap06ms95duKn8KQRfyE
?id=1VeKovyCt-iP1xiYfEatalHjDE69KVK8a
?id=1CYe74ah0jjDKNZD5Xdjtaeic4 t6xPjl
?id=1233i16u3otBLUEism4vEvT8s7g924T1A
?id=1DQ-b6ZemGLBUnDLq8C-qYuPD9ZEABEvH
?id=1QnOeh5AyNg6LXnee1gyFeLVb5VGNdiQD
?id=1o2ywPvJtFwclqsY0EbDPHLxWhEBQ8ml
?id=1m-2ITG9XixCs0KzzFTQNNZTuFzdaqLqy
?id=1xMlljN3JFUpEFP3lailHBc72KJ898Shb
?id=1esXyqZwa1L4Kq5-cUxK6FLNqsmFDteJQ
?id=1iMwiCyPIoi0mJ0i7B8JnKXDWYNbQWRNv
?id=1 79xQMse-rX0ce b3s6sfH7ahRCNHsok
?id=1jB4za1Pcf4Rx32KSsMGTEl-qsJ1IDqx8
?id=1WAFXzhwrNE7rmYm5CQyVcNxo2aoJuG1A
?id=1hVc1faCqRiFAFxfvSb9yjoHAW0pZKbSXO
?id=1wSWymQkVklUq8RGwiEacGAoTGhbuzpw0
?id=1wJTCOvC3fov97p gynivd2S V2msmEmB
?id=1BGIQnx1f8mroExZspThe5LLiO3UgtgX5
?id=1J6JWSzqJ3p1I821RWI7VryZPK-J QIKO
?id=1zTY1WxxlgCvWMx7T9Veh5nHopfbS-Miy
?id=1VmFFKwSLYlungspbOLiNIZLOz-CX51xV
?id=1AgXOQnVoSLybl2lmxwmm8EP9kZ3ieGW
?id=11jWZMiGlixBkDFTemr46TQjeXY6Z89tX
?id=1ggHtKhpra16WzidES22VTYv0wO 72U4F
?id=1cjY5SxM4cX8vke5ybi3Fsf4ldnt6weG9
?id=1YbnQXMDTsQFKbwcLavMLcXwbevg3blJ-
?id=1HNu8rfC7YDL9N-rhUui-9TJdvv6hAt77
?id=1CCI9PfwB3HhblbQSjm3200KpTFXbJkcW
?id=1cBI8fZtmbFzrBndqXbuP387BEfsawBg
?id=1yOwx2cf9qC8eV2LkNrglszU F-76mzW8
?id=1H7bNjqBWZTLwzAhffoBbW T2NO1wGS0X
?id=18faVPELAItae21Pgm v6bf5hJgGmxpFv
?id=1epq7C0tbvcgnIT16rGKRvLArIkwR08Eq
?id=1weadizXa1YwcMeF1UAoc0fZxDuMo6pLx
?id=15KfbPSXAsm4yET4CUW5yYIDzJ0tURBUz
?id=1qwx-5Sc8I6suctgle7itGDai-S7xTUgy
?id=1FZBmoCpYGX--qHFSw0NtTLQKyrSJug5g

?id=1IQ6bv-ToU6TEEnZNoqcdg0FE7pnviNmFB
?id=1zqP9uP_C96xUFqyaDmlo4JnKjHfs6F2
?id=1yUUDMdgEq_oTbGgl4onT5R23_QEo0np8
?id=1Wswlx4owNEhAqAyDk6R_d54Z7GGXEKbl
?id=1I9GS1g7Jb2hvMz8TfWAmyncJ-skB8F3L
?id=1Qu0UizIXjvyNH7DfX2LRKyX5wVF1XMP6
?id=1_GdgUta9_ZbSQokqKXj1AXSp79ZXWh8K
?id=1a-k_fUmddMG_fXhSCy2ghtYQT3O8Ynnx
?id=1sujqbKRO4CVQs_2rWBCikr_gfZl4TRhL
?id=1RHBlcwPtjwE8Y-Xp1xuBt2br-p_DjVBl
?id=1BGIXUrAQhTC-RE1MkKIm7WQpVO51Z4VM
?id=1to2ZHTdiJEY6mrZxUgfh2ZZrGebCdtWV
?id=10R0naPAtMlzb3NHhJkk6PHw8KAszPOA
?id=11u6wWDJDp3HjTT54At8pcvGJK-oxqxj6
?id=11NCdAcZ8SIQ4uzeb-hdFur-0hqN1wRtT
?id=1EmMQ6_ehlcCRjWWkTuQ57CWM2xNydkuA
?id=1bc-d9IEb3B8q2nsUx2p9ls20mruWclna
?id=1Rlqs9bljLonwmvtR5upWJ4OQsudNe4FA
?id=1A-OaWkjjw2iIRq6oWxAu3YsfedFlv08w
?id=1fyZwj4WgDeBcv1jtuq42Era28cXXNTaS
?id=1t9i4x083VNN6Ysbp484wP4qtW4eYgkn5
?id=1uPEpeGAnUer4aOPRxO3KpteWUgkaVplB
?id=1oJ_I0LlshDxPwWqxLuh197IoM-GJD_z
?id=1DVU2w_r3_R6QYR8oLFJ3HT1zdpaQUZkd
?id=1j253PFuGlf_OLoa_bfHb3srJu9RCd2vu
?id=1YjcMPt5aJByKryPTRVFrnrV-X71t-t8n
?id=1ISY35sxEhfUzWw9f-Ozrj4BpCsTU2hzS
?id=1QU0Yu5xfWxA8m0aPnwfirSurZy2sbpGR
?id=156gyZq8CkWI094lihrR6cSwRNAW_Oao
?id=19RONCH6o5aTGhowjCOXq-9wKe1LxjyuN
?id=1Xf20mlXmDRPXYS4IZv5xVLXU7g4zf5va
?id=1daxiihes5HePLW0R75RQp5Qmc8MhwnQp
?id=1t-dM6ImpgGf_apFZaWa-P678KFZBxHiJ
?id=18G16y8Ydslv0aveskZRadyQhMI1h1B7Q
?id=1OOe_lm3ulW3r3QX11OrDawy2Jlhv1xi3
?id=1fh58R9ylimmkW-997rFzC8SLxHGR5Eel
?id=1qnHv8bNk7cwf7C9qA215iSo-gKb3CM3L
?id=1pDTeysMs4irecesAwZi9HgKwisn_Es74
?id=1cnQhkI9Ka_gRmjI9vkosSJwqr24m5oDI
?id=1cVuG7L8rh6EFdAccXgoJ8rM5Mq-bXGyR
?id=160tkkKCJ9sSkYallL7Dy5zJU_D5-Pcaf
?id=1R0zCajLw4WC1fZSgrxdXBFS4dRx2cvj
?id=1LfBfVuk5kQeA0ieC50JTjbdTWHtrvfI
?id=10BKWJFLC1UfK21F-BkADLjGBaqV5hG2E
?id=1w8cL3FTfOTH_gjWzC1pDFVTdMpbivwRX
?id=1mObX1wz-4cKv3PFhe46EKn3crrF-Ve2I
?id=1Hw0JMGQfZ-lkuyD7dtKri-4oflQfPzVU
?id=14gcw-ABpcAqIOEpR6gK7z5JmCNDhZQst
?id=1XWFSnydsQtPdsyNb9BpLyqJqR_CMRJDG
?id=1B2FSXR6zxh-RariUDSifjynxwoviS9V
?id=1ynElebRI4vkbZVJdcBWica-U83B2OYb7
?id=16jAs9Mg06U8YUTrrNWqKilsSpAMpaEev
?id=14Re5ku9kXwsKvfBgviSrt1SwkseV93Zg
?id=1MC-Ahdp7j8imW32j9VD13gAwMcun7uU5
?id=1mu2F_Ft36twDPjIhb_AOTAmnS1UGwYkx
?id=16nJThdf8svbeoIAAELPknU2PhfKLq4kA
?id=1CLfmIpKO9etedJloDofY7pEzjtafLvR

?id=10om60CvfSRlcm2rHMn4R1wPQZIXngC-D
?id=1kxEwdd2z24-0ZjOBSlPjRHgJZWFgMImN
?id=1mPykJlPEm9s1UzGjEvqV9pgCB3nAYRV
?id=181Kg5xsZAOPs8oQ26yIFWSGcbjXJmrFJ
?id=1L86barbO9nY8A5QQI-zOG YXBbQ5fGIk
?id=1wHAJY1IfSYp2Yb tZ5J3gkaA8zn5E15b
?id=1RwsOr6VdkFwUDUsoknaBvKS21isKHt1d
?id=1pOq0SOjHj7E -JXILdgCV9IVb0k8j1W3
?id=1sbSPxujtpnaxM6ELpP8zoWZze6MxdSol
?id=1fvNygImnxanIri7cE2fwqyc-aMZafT-y
?id=1B973gT9mVlSkq3qTBB6l2ox24CIBBFJu
?id=14ktY3UAdnY2XkeFdGcyrkn98gT-lqqRT
?id=11ghmD6vVsPrPNwwEhOPubSU6maTbPZgl
?id=1jaVCzD 251ClxW8XvTQMmA-nVLjFxY4w
?id=17n9i6b1k4HvEHoyDma 5lFn7hFDb jYo
?id=1UPKK0aOjqHjSMmoKpffykRGjdRBM13lb
?id=1hJ-xzQ3hFXl7HJstYbEQPOf8N1n1 tmE